

[illegible]

FIG. 2




FIG. 2

FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D




FIG. 5A

FIG. 7A

FIG. 7A





FIG. 7B



T07260" T2909560

FIG. 7C




FIG.8




FIG. 8

FIG.9





FIG. 9

FIG. 10






FIG.12





FIG. 12

FIG.13





```

graph TD
    ST121{UNISSUED TICKET ?}
    ST123[OPERATE TICKET DISPENSER]
    ST125{TICKET DISPENSER RESPONDED ?}
    ST133{TICKET DISPENSER NOT RESPONDED FOR 2 SEC. ?}
    ST135[STOP TICKET DISPENSER]
    ST137[SOUND OUTPUT TO URGE REPLENISHMENT OF TICKETS  
(AT INTERVALS OF 10 SEC.)]
    ST139{TICKET REPLENISHMENT COMPLETION BUTTON ON ?}
    ST127[INCREMENT TICKET COUNTER]
    ST129{UNISSUED TICKET ?}
    ST131[STOP TICKET DISPENSER]

    ST121 -- NO --> ST121
    ST121 -- YES --> ST123
    ST123 --> ST125
    ST125 -- YES --> ST127
    ST125 -- NO --> ST133
    ST133 -- YES --> ST135
    ST133 -- NO --> ST125
    ST135 --> ST137
    ST137 --> ST139
    ST139 -- YES --> ST125
    ST139 -- NO --> ST139
    ST127 --> ST129
    ST129 -- YES --> ST121
    ST129 -- NO --> ST131
    ST131 --> ST123

```